MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town	Provincetown
Place (neighborhood or village)	
Address	11 ALDEN ST
Building ID	79
Parcel No. (PID)	12-1-042-0
Mapbase #	12-1-042
Building Area	1324.973
Historic Name	
Present Use	Residential
Original Use	Residential
Date of Construction	1950-1970
Source	NR Nomination
Style/Form	Contemporary
Architect/Builder	
Exterior Material	wood shingle
Foundation	concrete block
Wall/Trim	wood
Roof	side gable
Outbuildings/Secondary Structures	

Major Alterations (with dates)

Condition Good Moved 🖌 no 🗌 yes Date 0.062 Acreage **Recorded by** Vanessa Zeoli Setting Organization Kise Straw & Kolodner **Date** (month/year) April 2004 new Form Status update Assessor's Number USGS Quad Form Number Area(s)

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural feaures. Evaluate the characteristics of this building in terms of other buildings in the community.

11 Alden Street is a 1-story, 5-bay dwelling, oriented to the north. The side gable roof is clad in asphalt shingles, and the building is clad in wood shingles. Partial cornice returns; interior brick chimney. The former primary entrance, located in a 1-story gable roofed enclosed vestibule adjacent to the street, is no longer used; a storm door is suspended with no stair access. The primary entrance is now located on the north façade. Fenestration includes single-pane wood awning windows, and Chicago-style windows with fixed center window and flanking 4-pane casements are located on the west side. Retractable awnings shade windows adjacent to the street.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. If checked, you must attach a completed National Register Criteria Statement form.