MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown

Place (neighborhood or village)

Address 17 WEST VINE ST

Building ID 387

Parcel No. (PID) 06-2-054-0

Mapbase # 06-2-054

Building Area 1142.18

Historic Name

Present Use Residential
Original Use Residential

Date of Construction 1828

Source Tax assessment

Style/Form Astylistic

Architect/Builder

Exterior Material vinyl

Foundation stuccoed

Wall/Trim vinyl

Roof Side gable

Outbuildings/Secondary Structures

Smaller building on lot has been connected to this one.

Major Alterations (with dates)

Condition Good

Moved ✓ no ☐ yes Date

Acreage 0.103

Setting

Recorded by Vanessa Zeoli

Organization Kise Straw & Kolodner

Date (month/year) April 2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAI	ON				
FORM B - BUILDING	Ï				
ADOUGTOTUDAL DECORPOTION			•		•
ARCHITECTURAL DESCRIPTION see continuation sheet					
Describe architectural feaures. Evaluate the characteristics of this building in terms of other buildings in the community. 17 West Vine Street is composed of two dwellings connected by a hyphen. The larger section is 1-1/2-story, 3-bay, 1/2 cottage; side-gable roof is sheathed in asphalt shingles; fenestration includes 1/1 vinyl DHS windows throughout; main entrance is located on the right side of the front façade and contains a modern storm door that is reached by wood steps; gable dormer on front roof slope is clad in wood shingles; A 1-story, gable-roof hyphen on the rear façade connects this structure with a slightly smaller one behind it. The hyphen has a skylight and paired 1/1 vinyl DHS. The smaller dwelling is a 1-1/2-story, 2-bay structure; side-gable roof is sheathed in asphalt shingles; exterior brick chimney; fenestration includes a					
canted bay window with 1/1 vinyl DHS and a single-pane wo aluminum storm door; and a skylight on the front (west) roof	ood awning window; entra slope.	nce is accessed by a	a multi-pane wood d	oor with n	nodern
HISTORICAL NARRATIVE	see continuation sheet				
Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.					
BIBLIOGRAPHY and/or REFERENCES	see continuation sheet				
☐ Recommended for listing in the National Register of H	Historic Places. If checke	d, you must attach a	completed National	Register	
Criteria Statement form.					