

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 26 TREMONT ST
Building ID 778
Parcel No. (PID) 06-2-056-0
Mapbase # 06-2-056
Building Area 842.29
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1850-1870
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Condition Good
Moved no yes **Date**
Acreage 0.057
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

26 Tremont Street is a 2-story, 5-bay center entry building. The side-gable roof has interior end brick chimneys at each end, partial cornice returns at the gable ends, and a frieze below the eaves. Shed-roof wall dormers across most of the primary and rear facades provide the 2nd full story. The main entry is a panel door with storm, accessed by a concrete block and brick stoop. Windows are wood 2/2 and 6/1 wood DHS. 2/1 DHS are located at the basement level. An exterior stair at the rear and deck around the side provide access to secondary entries at the rear 1st story and west side 2nd story.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*