

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 7 WEST VINE ST
Building ID 1753
Parcel No. (PID) 06-2-058-0
Mapbase # 06-2-058
Building Area 1158.025
Historic Name
Present Use Residential
Original Use Unknown
Date of Construction 1870-1890
Source Tax Assessment
Style/Form Astylistic
Architect/Builder
Exterior Material wood shingle
Foundation obscured
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Condition Good
Moved no yes **Date**
Acreage 0.071
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

7 West Vine is a 2-story, 6-bay dwelling; side-gable roof is sheathed in asphalt shingles; exposed rafter ends; interior brick chimney; north façade has two end entrances with wood panel doors and aluminum storms; entrances are both sheltered by a gable-front entry porch supported by square posts with a built-in bench on 1 side; next to entry doors is a 20-pane wood picture window flanked by 4/4 wood DHS; between the picture windows are 6/6 wood DHS with operable shutters; the 2nd floor contains 2 shed wall dormers with paired 8/8 wood DHS windows flanking two 6/6 wood DHS with operable shutters and a shallow balcony with balustrade and is supported by brackets; a canted bay window on the west facade has a hipped roof and paired 6/6 wood DHS flanked by 4/4 wood DHS; 6/6 wood DHS in the gable end with inoperable shutters; rear (south) elevation contains exterior wood steps to a 2nd-story porch with entrances.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*