MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town	Provincetown
Place (neighborhood or village)	
Address	18 FRANKLIN ST
Building ID	422
Parcel No. (PID)	06-4-086-0
Mapbase #	06-4-086
Building Area	1091.239
Historic Name	
Present Use	Residential - Multi-unit
Original Use	Residential
Date of Construction	1800-1830
Source	NR Nomination
Style/Form	Astylistic
Architect/Builder	
Exterior Material	wood shingle
Foundation	brick
Wall/Trim	wood
Roof	Side gable
Outbuildings/Secondary Structures	

Major Alterations (with dates) Rear additions; multi-unit conversion.

Condition Moved Acreage Setting Good ✓ no □ yes Date 0.095

Recorded by Organization Date (month/year) Form Status Assessor's Number Johnette Davies Kise Straw & Kolodner April 2004 Inew Indate USGS Quad Area(s)

Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural feaures. Evaluate the characteristics of this building in terms of other buildings in the community.

18 Franklin Street is a 2-story, 5-bay dwelling with side gable roof and central entry. The primary façade is clad in clapboard, and wood shingles clad the secondary facades. The main entry has a replacement door and slight shed-roofed hood. Secondary entrances are located on the north facade - 1 at each story - toward the rear of the building. Wood decks are present at both entries, with the 2nd story deck wrapping around to the rear. Windows are generally 2/2 wood DHS with aluminum storms; 2/1 and 1/1 DHS are present on the north facade. A 1-story section at rear has a roof deck above.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. If checked, you must attach a completed National Register Criteria Statement form.