

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place (*neighborhood or village*)
Address 11 CENTRAL ST
Building ID 87
Parcel No. (PID) 07-2-104-0
Mapbase # 07-2-104
Building Area 1439.785
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1830-1850
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation stuccoed
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures
 1 garage; attached cottage

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Major Alterations (with dates)

Entry and window sash (20th cent.)

Condition Good
Moved no yes **Date**
Acreage 0.088
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (*month/year*) April 2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

11 Central Street is a 1 1/2-story, 3-bay center entry, Greek Revival-style cottage. The building is clad in wood shingles, with staggered shingles at the cornice at the north and south facades. The front gable roof is clad in asphalt shingles; partial returns; interior brick chimney at peak. Corner pilasters present. The main entry consists of a pane and panel wood door with modern storm; raised entrance; brick deck and steps accessed from the south side; door under pedimented entry porch supported by square posts; simple balustrade. Fenestration includes 1/1 DHS wood with storms; inoperable shutters. A 1-story gable roof addition with brick interior chimney extends from the east gable end. This addition connects to a gable cottage, which is 1 story with a cross gable roof.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*