

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 10 PEARL ST
Building ID 44
Parcel No. (PID) 12-1-100-0
Mapbase # 12-1-100
Building Area 1044.477
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1850
Source Tax assessment
Style/Form Italianate
Architect/Builder
Exterior Material wood shingle
Foundation brick
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures
 1 cottage

Major Alterations (with dates)

sash and entry altered (1970s); replacement fenestration.

Condition Good
Moved no yes **Date**
Acreage 0.069
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

10 Pearl St. is a 1 1/2-story, 2-bay sidehall cottage. The front-gable roof has partial returns; pendant brackets below the eaves; brick chimney at roof ridge; gable dormer in south roof slope. Main entry consists of a replacement door with simple wood surround; concrete stoop. Secondary entrance on south facade with flat hood and pendant end brackets. Fenestration includes 1/1 wood DHS replacements; 1 Chicago-style picture window present on south facade. 1-story rear ell with shed dormer on north roof slope.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*